

SAFE ACID™ O&G+PLUS

Environmentally Friendly Well Treatment

HAZARD STATEMENTS: MAY CAUSE SKIN IRRITATION. MAY CAUSE EYE IRRITATION. MAY BE HARMFUL IF SWALLOWED.

Safe Acid O&G Plus is a safe hydrochloric acid alternative for improving well production and flow in pipes.

Non-corrosive to skin and most metals. 100% biodegradable.

DIRECTIONS: Product may be used at 1:1 to 1:4 dilution. Dilution rates vary based on the specific application. Contact your Enviro Tech sales representative For instruction and uses.

D.O.T. and Hazard Information: Non-regulated Material, Liquid
Contains no hazardous ingredients.

NET CONTENTS: 330 GAL.

PRECAUTIONARY STATEMENT:

Wear protective gloves/ eye protection
Do not eat, drink, or smoke when using this product
Do not breathe dust/fume/gas/mist/vapors/spray

IF IN EYES: rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do. Continue rinsing.

IF ON SKIN: remove/ take off immediately all contaminated clothing. Rinse skin with water/shower.

IF SWALLOWED: rinse mouth. Do not induce vomiting. Call a poison center or doctor/physician.

STORAGE AND DISPOSAL:

STORAGE: Keep product dry in tightly closed original container when not in use. Store in a cool, dry, well-ventilated area. Product should be stored at 50° F or above.

DISPOSAL: Wastes resulting from the use of this product may be disposed of on site or at an approved waste disposal facility. DO NOT REUSE EMPTY CONTAINER. Triple rinse the container (or equivalent). Then offer for recycling or reconditioning, or puncture and dispose of in a sanitary landfill, or incinerate.

**KEEP OUT OF THE REACH OF CHILDREN.
FOR INDUSTRIAL or FOOD PLANT USE ONLY**

HMIS RATINGS:

HEALTH	1
FLAMMABILITY	0
REACTIVITY	0
PERSONAL PROTECTION	B

HMIS HAZARD EXPOSURE RATING:
0=Minimal; 1=Slight; 2=Moderate; 3= High;
4=Extreme

PERSONAL PROTECTION

GUIDE :

A = Safety Glasses
B = Safety Glasses & Gloves
C = Safety Glasses, Gloves, Protective Suit & Boots
D = Gloves, Protective Suit & Boots, & Face Shield
E = Safety Glasses, Gloves & Dust Mask
F = Safety Glasses, Gloves, Protective Suit & Boots & Dust Mask
G = Safety Glasses or Face Shield, Gloves & Vapor Respirator
H = Safety Glasses, Gloves, Protective Suit & Boots, & Vapor Respirator
X = Special Equipment

Modern Solutions by:



CHEMICAL SERVICES, INC.
MODESTO, CA 95358

www.envirotech.com

**24 Hour Emergency Transportation
Number: 1-800-424-9300**

670-WT100