

# SAFE ACID™ O&G

## Environmentally Friendly Well Treatment DANGER

**HAZARD STATEMENTS: CAUSES SEVERE SKIN BURNS AND EYE DAMAGE. CAUSES SERIOUS EYE IRRITATION.**

Safe Acid O&G is a safe hydrochloric acid alternative for improving well production and flow in pipes.

Non-corrosive to skin and most metals. 100% biodegradable.

**DIRECTIONS:** Product may be used at 1:1 to 1:4 dilution. Dilution rates vary based on the specific application. Contact your Enviro Tech sales representative For instruction and uses.

**D.O.T. and Hazard Information:**

# UN3265

**Corrosive Liquid, Acidic, Organic, n.o.s. (Containing Amines), 8, PG II**

### PRECAUTIONARY STATEMENT:

Wash hands thoroughly after handling

Wear protective gloves/protective clothing/eye protection/face protection.  
Immediately call a POISON CENTER or doctor/physician.

Wash contaminated clothing before reuse.

For specific treatment see Section 4 First Aid.

**IF SWALLOWED:** Rinse mouth. Do NOT induce vomiting.

**IF ON SKIN (or hair):** Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower.

**IF IN EYES:** Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do.

**IF INHALED:** Remove victim to fresh air and keep at rest in a position comfortable for breathing.

### STORAGE AND DISPOSAL:

Store locked up.

Dispose of contents/container in accordance with local regulations.

**KEEP OUT OF THE REACH OF CHILDREN.  
FOR INDUSTRIAL or FOOD PLANT USE ONLY**

NET CONTENTS: 330 GAL.

### HMIS RATINGS:

HEALTH	3
FLAMMABILITY	0
REACTIVITY	0
PERSONAL PROTECTION	D

HMIS HAZARD EXPOSURE RATING:  
0=Minimal; 1=Slight; 2=Moderate; 3= High;  
4=Extreme

### PERSONAL PROTECTION GUIDE :

A = Safety Glasses  
B = Safety Glasses & Gloves  
C = Safety Glasses, Gloves, Protective Suit & Boots  
D = Gloves, Protective Suit & Boots, & Face Shield  
E = Safety Glasses, Gloves & Dust Mask  
F = Safety Glasses, Gloves, Protective Suit & Boots & Dust Mask  
G = Safety Glasses or Face Shield, Gloves & Vapor Respirator  
H = Safety Glasses, Gloves, Protective Suit & Boots, & Vapor Respirator  
X = Special Equipment



Modern Solutions by:



**CHEMICAL SERVICES, INC.**  
MODESTO, CA 95358

[www.envirotech.com](http://www.envirotech.com)

**24 Hour Emergency Transportation  
Number: 1-800-424-9300**

**673-WT100 REV.2**