

# **Environmentally Friendly Well Treatment**

HAZARD STATEMENTS: CAUSES SEVERE SKIN BURNS AND EYE DAMAGE. CAUSES SERIOUS EYE DAMAGE.

Safe Acid NHF is a safe ABF/hydrofluoric acid alternative for improving well production and flow in pipes.

Non-corrosive to skin and most metals. 100% biodegradable.

**DIRECTIONS:** Dilution rates vary based on the specific application. Contact your Enviro Tech sales representative for instruction and uses.

**D.O.T. and Hazard Information:** 

UN3265

Corrosive liquid, acidic, organic, n.o.s. (containing amines),8, PG II

#### PRECAUTIONARY STATEMENT:

Wash hands thoroughly after handling
Wear protective gloves/protective clothing/eye protection/face protection.
Wash contaminated clothing before reuse.
For specific treatment see Section 4 First Aid.

IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.

IF ON SKIN (or hair): Remove/Take off immediately all co

**IF ON SKIN (or hair):** Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. **IF IN EYES**: Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do. **IF INHALED**: Remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor/physician.

#### STORAGE AND DISPOSAL:

Store locked up.

Dispose of contents/container in accordance with local regulations.

Do not store product in any kind of glass container, product is corrosive to glass and silicates.

KEEP OUT OF THE REACH OF CHILDREN. FOR INDUSTRIAL or FOOD PLANT USE ONLY

NET CONTENTS: 330 GAL

#### **HMIS RATINGS:**

HEALTH	3
FLAMMABILITY	0
REACTIVITY	0
PERSONAL PROTECTION	D

#### HMIS HAZARD EXPOSURE RATING:

0=Minimal; 1=Slight; 2=Moderate; 3= High; 4=Extreme

### **PERSONAL PROTECTION GUIDE:**

- A = Safety Glasses
- B = Safety Glasses & Gloves
- C = Safety Glasses, Gloves, Protective Suit & Boots
- D = Gloves, Protective Suit & Boots, & Face Shield
- E = Safety Glasses, Gloves & Dust Mask
- F = Safety Glasses, Gloves, Protective Suit & Boots & Dust Mask
- G = Safety Glasses or Face Shield, Gloves & Vapor Respirator
- H = Safety Glasses, Gloves, Protective Suit & Boots, & Vapor Respirator
- X = Special Equipment



## **Modern Solutions by:**



CHEMICAL SERVICES, INC.

MODESTO, CA 95358

www.envirotech.com

24 Hour Emergency Transportation Number: 1-800-424-9300

980-WT100